


Screw in- Resistance Temperature Sensor Typenreihe : CHS



sensor resistor : Pt 100 Ω
at 0°C (DIN EN 60751) Kl. B
2 x Pt 100 Ω
at 0°C (DIN EN 60751) Kl. B

(other designs available)

small connecting head : \varnothing 48 mm

thread : G 3/8"
G 1/2"
G 3/4"

depth of immersion : L to customer incl. thread

immersion sleeve : \varnothing to customer (VA)

operation temperature : depending on version
up to max. 400°C

**Other customer preferences are possible
Subject to modifications!**

13/07